

Major References

Service Division



Reference list

Power Plant	Owner	Country	Type of work	Year
Walsum, 9	Evonik	Germany	Revision APH	2011
Frövi Bark boiler	Korsnäs AB	Sweden	Revision on boiler	2011
Longyear Energiverk	Longyear Energiverk	Norway	Revision & chemical cleaning	2011
Värö Bark boiler	Södra Cell AB	Sweden	Retrofit	2011
Ena Biomass boiler	ENA Energi AB	Sweden	Spare parts for revision	2011
Skærbæk	DONG Energy	Denmark	Chemical cleaning	2011
Uppsala KVV	Vattenfall AB Värme	Sweden	Revision on boiler	2011
Fyn	Vattenfall A/S	Denmark	Spare parts for revision	2011
Avedøre	DONG Energy	Denmark	District heating deaerator	2011
Ena Biomass boiler	ENA Energi AB	Sweden	Revision	2010
Herning	DONG Energy	Denmark	Pipes for dust dosing	2010
Uppsala, 1	Vattenfall AB Värme	Sweden	Repair of boiler	2010
Skærbæk, 3	Dong Energy	Denmark	Installation of pin rack	2010
Avedøre	Dong Energy	Denmark	Changes for coal	2010
Herning	Dong Energy	Denmark	Eco Bypass	2010
Uppsala KVV	Vattenfall Värme AB	Sweden	Engineering, design and delivery hot reheat pipe	2010
H.C. Ørsted	Dong Energy	Denmark	8 gas rings and 6 gas lances per ring	2010
Ena Biomass boiler	ENA Energi AB	Sweden	Revision	2010
La Spezia	ENEL	Italy	Burners & Spare parts	2010
West Burton	EDF Energy	U.K.	Supervision for pipe installation	2010
Viborg KV	Viborg Kraftvarme A/S	Denmark	Repair of hopper	2010
Frövi Bark boiler	Korsnäs AB	Sweden	Replacement of primary & secondary Superheater	2010
Uppsala, 4	Vattenfall AB Värme	Sweden	Replacement of economiser, roof for furnace	2009
Uppsala KVV	Vattenfall AB Värme	Sweden	Revision on boiler and DeNOx plant	2009
Uppsala	Vattenfall AB Värme	Sweden	Installation of tube system for turbine x	2009
Uppsala, 4	Vattenfall AB Värme	Sweden	Replacement of part of membrane wall 1 & 2 draft	2009
Avedøre, 2	Dong Energy	Denmark	Revision on drain pipe	2009
Herning	Dong Energy	Denmark	Inspection and revision on APH	2009
Maribo-Sakskøbing	Dong Energy	Denmark	Replacement of OH 1.2	2009
Avedøre, 2	Dong Energy	Denmark	Replacement of PA cooler and duct	2009
Kyndby	Dong Energy	Denmark	Cloth below upper pass correction	2009
Skærbæk, 3/Avedøre, 2	Dong Energy	Denmark	Burner parts	2009
Stignæs	Dong Energy	Denmark	Replacement of panel wall	2009
Asnæs, 5	Dong Energy	Denmark	Revision of air preheater	2009
Ensted, 3	Dong Energy	Denmark	HTS Superheater Replacement	2009
Uppsala, 1	Vattenfall AB Värme	Sweden	Manufacture and delivery of 50m ² panel wall	2009
Uppsala, 1	Vattenfall AB Värme	Sweden	Design and erection of ECO	2009
Bolandsverket	Vattenfall AB Värme	Sweden	Installation of valves for condensate	2009
Nordjylland, 3	Vattenfall A/S	Denmark	Assistance on air preheater	2009
Fyn, 6+7	Vattenfall A/S	Denmark	Revision	2009
Ena Biomass boiler	ENA Energi AB	Sweden	Grate elements	2009
Ena Biomass boiler	ENA Energi AB	Sweden	Inspection of Boiler	2009
Hylte, 2	Stora Enso AB	Sweden	Replacement of 24 super heaters	2009
Frövi Bark boiler	Korsnäs AB	Sweden	Design and erection of super heater	2009
Uppsala 1	Vattenfall AB Värme	Sweden	Replacement of grate	2008
Avedøre, 2	Dong Energy	Denmark	Assistance on mill project	2008
Avedøre, 2	Dong Energy	Denmark	Manufacture and replacement of 4 outlet headers	2008
Uppsala KVV	Vattenfall Värme AB	Sweden	Delivery and Erection of panel wall	2008
Uppsala KVV	Vattenfall Värme AB	Sweden	Erection of panel wall	2008
Avedøre, 2	Dong Energy	Denmark	Delivery of pipes for drain	2008
Fyn, 7	Vattenfall A/S	Denmark	Revision	2008
Amager, 3	ENERGI E2	Denmark	Replacement of pipe section	2008
Fyn, 6&7	Elsam Kraft A/S	Denmark	Assistance on boilers (Revision)	2008
Fyn, 7	Elsam Kraft A/S	Denmark	OBA nozzles and various burner parts	2008
Fyn, 7	Elsam Kraft A/S	Denmark	Replacement of flue gas compensators	2008
Masnedø	Elsam Kraft A/S	Denmark	Retrofit of secondary air system	2008
Masnedø	Elsam Kraft A/S	Denmark	Replacement of sluice gates for straw	2008
Mälarenergi, 4	Mälarenergi AB	Sweden	Retrofit of air preheater	2008
Värö Bark boiler	Södra Cell AB	Sweden	Replacement and retrofit of Kablitz grate	2008
Brindisi	Enel Produzione S.p.A.	Italy	Gas-gas heater spare parts	2008
H.C. Ørsted	Energi E2 A/S	Denmark	Engineering and reparation of end caps on headers	2008





Power Plant	Owner	Country	Type of work	Year
Skærbæk, 3	Dong Energy	Denmark	Retrofit of HP bypass injection	2007
Asnæs, 5	ENERGI E2	Denmark	Revision of boiler	2007
Asnæs, 4	ENERGI E2	Denmark	Exchange of headers	2007
Asnæs, 2	ENERGI E2	Denmark	Revision	2007
Ildbäckverket, 3	Vattenfall AB Värme	Sweden	94 Super Heaters	2007
Stignæs, 2	ENERGI E2	Denmark	Replacement / Retrofit of APH elements	2007
Ildbäckverket, 3	Vattenfall AB Värme	Sweden	Reparation and Replacement of ECO	2007
Uppsala KVV	Vattenfall AB Värme	Sweden	Replacement of tubes and evaporator	2007
Ildbäckverket	Vattenfall AB Värme	Sweden	Exchange of panel walls CFB boiler	2007
Nordjylland, 3	Vattenfall A/S	Denmark	Revision and acid cleaning	2007
Ena Biomass boiler	ENA Energi AB	Sweden	Delivery of air preheater heating elements	2007
Amager, 3	ENERGI E2	Denmark	Revision on gas-gas heater	2007
Fyn 3	Elsam Kraft A/S	Denmark	Replacement of 168 basket in APH	2007
Køge KVV	ENERGI E2	Denmark	Replacement of SH 2,2 in BWE boiler	2007
Silkeborg KW	Silkeborg Kraftvarmeværk	Denmark	Erection HP valve incl. various calculations	2007
Uppsala KVV	Vattenfall AB Värme	Sweden	New Burner openings	2006
Uppsala KVV	Vattenfall AB Värme	Sweden	Revision of boiler	2006
Avedøre, 1&2	ENERGI E2	Denmark	Revision	2006
Avedøre, 2	ENERGI E2	Denmark	Flue gas recirculation ducts	2006
Avedøre, 1	ENERGI E2	Denmark	Replacement of 60m ² boiler wall	2006
Avedøre, 1	ENERGI E2	Denmark	Upgrade	2006
Asnæs, 5	ENERGI E2	Denmark	Assistance at revision	2006
Uppsala, 4	Vattenfall AB Värme	Sweden	Retrofit of grates	2006
Ildbäckverket, 3	Vattenfall AB Värme	Sweden	4 weavings	2006
Fyn, 6	Vattenfall A/S	Denmark	Replacement of ceiling above furnace	2006
Ena Biomass boiler	ENA Energi AB	Sweden	Revision	2006
Nordjylland, 3	Elsam Kraft	Denmark	Revision	2006
Svalbard, 1	Svalbard Samfunnsdrift	Norway	Revision of boiler	2006
Svalbard, 1	Svalbard Samfunnsdrift	Norway	Wearing parts grate	2006
Masnød	ENERGI E2	Denmark	Erection of FG ducts	2006
Frövi	AssiDomän Frövi	Sweden	Design and Installation of super heaters	2006
Rugeley Power Station	Rugeley Power Ltd.	U.K.	1 stk. Low NOx burner	2006
Uppsala KVV	Vattenfall AB Värme	Sweden	Retrofit of air preheater	2005
Uppsala KVV	Vattenfall AB Värme	Sweden	Replacement of lower part of superheater 3	2005
Avedøre 1&2	ENERGI E2	Denmark	Revision	2005
Avedøre, 2	ENERGI E2	Denmark	Gas-gas heater elements incl. installation	2005
Avedøre, 2	ENERGI E2	Denmark	Work on intermediate pressure pipes	2005
Asnæs, 5	ENERGI E2	Denmark	Welding of 4 T pieces for mainstream pipe	2005
Uppsala KVV	Vattenfall AB Värme	Sweden	Design and Installation of DeNox system	2005
Stignæs, 2	ENERGI E2	Denmark	Installation of 12 OFA nozzles	2005
Stignæs, 2	ENERGI E2	Denmark	Revision of 2 air preheaters	2005
Stignæs, 2	ENERGI E2	Denmark	Delivery and installation of hot reheater pipes	2005
Stignæs	ENERGI E2	Denmark	Various gallery work	2005
Ena Biomass boiler	ENA Energi AB	Sweden	Inspection of soot blower system	2005
Amager, 1	ENERGI E2	Denmark	Assistance on gas-gas heater	2005

BURMEISTER & WAIN ENERGY A/S
 Lundtoftøgårdsvej 93A
 DK-2800 Kgs. Lyngby, Denmark
 Tel. +45 39 45 20 00
 Fax. +45 39 45 20 05
 E-mail: info@bwe.dk
 Http://www.bwe.dk

BWE-20-001&rev.1